DIN EN ISO 6892-2:2026-11 (E)

Metallic materials - Tensile testing - Part 2: Method of test at elevated temperature (ISO 6892-2:2026)

Contents

Page

Foreword ... iv

Introduction ... v

1 Scope ... 1

2 Normative references ... 1

3 Terms and definitions ... 1

4 Symbols ... 2

5 Principle ... 2

6 Test piece ... 3

7 Determination of original cross-sectional area (S_o) ... 3

8 Marking the original gauge length (L_o) ... 3

9 Apparatus ... 3

10 Test conditions ... 4

10.1 Setting the force zero point ... 4

10.2 Gripping of the test piece, fixing of the extensometer and heating of the test piece, not necessarily in the following sequence ... 5

10.2.1 Method of gripping ... 5

10.2.2 Fixing of the extensometer and establishing the gauge length ... 5

10.2.3 Heating of the test piece ... 6

10.3 Testing rate based on strain rate control (Method A) ... 6

10.3.1 General ... 6

10.3.2 Strain rate for the determination of the upper yield strength (R_{eH}) or proof strength properties (R_p and, if required, R_t) ... 6

10.3.3 Strain rate for the determination of the lower yield strength (R_{eL}) and percentage yield point extension (A_e), if required ... 6

10.3.4 Strain rate for the determination of the tensile strength (R_m), percentage elongation after fracture (A), percentage reduction area (Z), and, if required, percentage total extension at the maximum force (A_{gt}), percentage plastic extension at maximum force (A_g) ... 7

10.4 Method of testing with expanded strain rate ranges (Method B) ... 7

10.4.1 General ... 7

10.4.2 Rate for the determination of yield strength or proof strength properties ... 7

10.4.3 Rate for the determination of tensile strength ... 7

10.5 Choice of the method and rates ... 8

10.6 Documentation of the chosen testing conditions ... 8

11 Determination or calculation of the properties ... 8

12 Test report ... 8

13 Measurement uncertainty ... 9

14 Figures ... 9

15 Annexes ... 10

Annex A (informative) **Additional information regarding test piece geometries used for testing at elevated temperature** ... 11

Annex B (informative) **Measurement uncertainty** ... 17

Bibliography ... 20