ISO 7539-6:2003-02 (E)

Corrosion of metals and alloys - Stress corrosion testing - Part 6: P reparation and use of pre-cracked specimens for tests under constant load or constant displacement

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Principle 4

5 Specimens 5

6 Initiation and propagation of fatigue cracks 23

7 Procedure 25

8 Test report 33

Annex A (normative) Use of notched specimens for stress corrosion tests 35

Annex B (normative) Determination of crack growth velocity 38