ISO 17636:2003-09 (E)

Non-destructive testing of welds - Radiographic testing of fusion-welded joints

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviations 2

5 Classification of radiographic techniques 3

6 General 3
6.1 Protection against ionizing radiation 3
6.2 Surface preparation and stage of manufacture 3
6.3 Location of the weld in the radiograph 3
6.4 Identification of radiographs 3
6.5 Marking 3
6.6 Overlap of films 4
6.7 Types and positions of image quality indicators (IQI) 4
6.8 Evaluation of image quality 4
6.9 Minimum image quality values 5
6.10 Personnel qualification 5

7 Recommended techniques for making radiographs 5
7.1 Test arrangements 5
7.2 Choice of tube voltage and radiation source 15
7.3 Film systems and screens 17
7.4 Alignment of beam 19
7.5 Reduction of scattered radiation 19
7.6 Source-to-object distance 19
7.7 Maximum area for a single exposure 21
7.8 Density of radiograph 22
7.9 Processing 22
7.10 Film viewing conditions 22

8 Test report 22

Annex A (normative) Minimum image quality values for ferrous materials 24

Annex B (informative) Recommended number of exposures for acceptable testing of a circumferential butt weld 30

Bibliography 35