ISO 16700:2004-03 (E)

Microbeam analysis - Scanning electron microscopy - Guidelines for calibrating image magnification

---

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Image magnification 3
4.1 Scale marker 3
4.2 Expressing magnification 3

5 Reference material 4
5.1 General 4
5.2 Requirements for CRM 4
5.3 Pitch patterns on CRM 4
5.4 Storage and handling 4

6 Calibration procedures 5
6.1 General 5
6.2 Mounting CRM 5
6.3 Setting SEM operation conditions for calibration 5
6.4 Image recording 6
6.5 Measurement of image 6
6.6 Calibration of magnification and scale marker 7

7 Accuracy of image magnification and scale marker 8

8 Calibration report 9
8.1 General 9
8.2 Contents of calibration report 9

Annex A (informative) Reference materials for magnification 10

Annex B (informative) Parameters that influence the resultant magnification of an SEM 12

Annex C (informative) Uncertainties in magnification measurements 14

Annex D (informative) Example of a test report 15