ISO 19318:2004-05 (E)

Surface chemical analysis - X-ray photoelectron spectroscopy - Reporting of methods used for charge c ontrol and charge correction

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative reference 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 1

5 Apparatus 2

6 Calibration of binding-energy scale 2

7 Reporting of information related to charge control 2
7.1 Methods of charge control 2
7.2 Information on specimen 2
7.3 Instrument and operating conditions 3
7.4 General method for charge control 3
7.5 Reasons for needing charge control and for choosing the particular method for charge control 3
7.6 Values of experimental parameters 3
7.7 Information on the effectiveness of the method of charge control 4

8 Reporting of method(s) used for charge correction and the value of that correction 4
8.1 Methods of charge correction 4
8.2 Approach 4
8.3 Value of correction energy 4

Annex A (informative) Description of methods of charge control and charge correction 5

A.1 Introduction 5
A.2 Methods of charge control 5
A.3 Methods of charge correction 7
A.4 Bias referencing [17] 8
A.5 Auger parameter measurements [32-34] 9

Bibliography 10