ISO 24237:2005-06 (E)

Surface chemical analysis - X-ray photoelectron spectroscopy - Repeatability and constancy of intensity scale

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Symbols and abbreviations 1

3 Outline of method 2

4 Method for evaluating the repeatability and constancy of the intensity scale 2
4.1 Obtaining the reference sample 2
4.2 Mounting the sample 3
4.3 Cleaning the sample 3
4.4 Choosing the spectrometer settings for which intensity stability is to be determined 4
4.5 Operating the instrument 5
4.6 Options for initial or subsequent evaluation measurements 5
4.7 Measurements for the intensity and repeatability 5
4.8 Calculating the peak area intensities, intensity ratios and uncertainties 6
4.9 Procedure for the regular evaluation of the constancy of the intensity scale 7
4.10 Next evaluation 7

Annex A (informative) Example of calculations and measurements of the intensity repeatability for a commercial X-ray photoelectron spectrometer using unmonochromated Mg K X-rays 9

Bibliography 12