ISO 17492:2019-10 (E)

Clothing for protection against heat and flame - Determination of heat transmission on exposure to both flame and radiant heat

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 3

5 Apparatus 4

6 Precautions 8

7 Sampling 9
7.1 Specimen dimensions 9
7.2 Number of specimens 9

8 Conditioning and testing atmospheres 9
8.1 Conditioning atmosphere 9
8.2 Testing atmosphere 9

9 Test procedure 9
9.1 Initial set up and calibration procedures 9
9.1.1 Initial set up of the system and alignment of burner flames 9
9.1.2 Initial setting of the 50/50 mix of convective and radiant heat 9
9.1.3 Setting the radiant heat from the lamps 9
9.1.4 Setting the total exposure heat flux 10
9.2 Sensor care 10
9.2.1 Sensor care 10
9.2.2 Sensor inspection 10
9.2.3 Surface reconditioning 10
9.3 Specimen holder care 11
9.4 Computer processing of data 11
9.5 Test specimen mounting 12
9.5.1 Single layer specimens 12
9.5.2 Multilayer assembly specimens 12
9.6 Test specimen exposure when both TPI and HTI(DE) are measured 12
9.7 Test specimen exposure when only HTI(DE) is measured 13

10 Expression of results 13
10.1 Selection of analysis method 13
10.2 Thermal protection index analysis method 13
10.2.1 Time to onset of burn injury 13
10.2.2 Thermal protection index 13
10.3 HTI(DE) analysis method 14
10.4 Response to convective and radiant heat exposure 14

11 Interlaboratory test data 14

12 Test report 14

Annex A (informative) Availability of materials 15

Annex B (informative) Basis of sensor calibration 17

Annex C (informative) Interlaboratory test data 18

Bibliography 19