DIN EN ISO 13506-1:2024-12 (E)

Protective clothing against heat and flame - Part 1: Test method for complete garments - Measurement of transferred energy using an instrumented manikin (ISO 13506-1:2024)

Contents

Page

European foreword ... **4**

Foreword ... **5**

Introduction ... **6**

1 Scope ... **7**

2 Normative references ... **7**

3 Terms and definitions ... **8**

4 Overview ... **10**
4.1 General ... 10
4.2 Heat flux - energy balance on the sensor ... 10
4.3 Assumptions to achieve the required heat flux ... 11

5 Apparatus ... **12**
5.1 Instrumented manikin ... 12
5.2 Posture of the manikin ... 15
5.3 Manikin sensors ... 16
5.3.1 Principle ... 16
5.3.2 Number of manikin sensors ... 17
5.3.3 Manikin sensor-measuring capability ... 18
5.3.4 Manikin sensor specification ... 18
5.3.5 Manikin sensor positioning ... 20
5.3.6 Manikin heat flux validation ... 20
5.4 Data acquisition system ... 22
5.5 Computer software program ... 22
5.5.1 General ... 22
5.5.2 Incident heat flux ... 23
5.5.3 Exposure heat flux ... 23
5.5.4 Thermal manikin protection factor (TMPF) ... 23
5.5.5 Transferred energy ... 24
5.6 Flame exposure chamber ... 25
5.6.1 General ... 25
5.6.2 Chamber size ... 25
5.6.3 Chamber air flow ... 25
5.6.4 Chamber isolation ... 25
5.6.5 Chamber air exhaust system ... 25
5.6.6 Chamber safety devices ... 25
5.7 Fuel and delivery system ... 26
5.7.1 General ... 26
5.7.2 Fuel ... 26
5.7.3 Fuel delivery and shut-off system ... 26
5.7.4 Burner system ... 26
5.8 Image recording equipment ... 27
5.9 Safety checklist ... 27
5.10 Laboratory capability demonstration ... 28

6 Sampling and test specimens ... **28**
6.1 General ... 28
6.2 Number of test specimens ... 28
6.3 Size of test specimen ... 28
6.4 Specimen preparation ... 29

6.4.1 Conditioning 29
6.4.2 Optional laundering 29
6.5 Standard reference garment design 29

7 Pre-requisites for products implementing this test method 30

8 Procedure 31
8.1 Preparation of test apparatus 31
8.1.1 General 31
8.1.2 Manikin sensor check 31
8.1.3 Flame exposure chamber purging 32
8.1.4 Confirming safe operation conditions and lighting of pilot flames 32
8.1.5 Gas line charging 32
8.1.6 Confirmation of nude and garment exposure conditions 32
8.2 Specimen testing procedure 33
8.2.1 General 33
8.2.2 Dressing the manikin 33
8.2.3 Recording the specimen identification, test conditions and test observations 34
8.2.4 Starting the image recording system 34
8.2.5 Setting time for heat transfer data acquisition 35
8.2.6 Exposure of the test specimen 35
8.2.7 Recording of specimen response remarks 35
8.2.8 Calculation of surface incident heat flux and transferred energy 35
8.2.9 Still images 35
8.3 Preparing for the next test exposure 35

9 Test report 36
9.1 General 36
9.2 Specimen identification 36
9.3 Exposure conditions 36
9.4 Results for each specimen 37
9.4.1 General 37
9.4.2 Heat flux data of each manikin sensor 37
9.4.3 Thermal manikin protection factor 37
9.4.4 Transferred energy 37
9.4.5 Other information that may be reported 38
9.5 Observations 38

Annex A (informative) **Considerations for conducting tests and using test results 39**

Annex B (informative) **Interlaboratory test data analysis 40**

Annex C (normative) **Calibration and validation procedure 42**

Annex D (informative) **Burner stand alignment for flame engulfment 45**

Annex E (informative) **Elements of a computer software program 48**

Bibliography 50