ISO 7870-7:2020-02 (E)

Control charts - Part 7: Multivariate control charts

Contents

Page

Foreword ... **iv**

Introduction ... **v**

1 Scope ... **1**

2 Normative references ... **1**

3 Terms and definitions ... **1**

4 Abbreviated terms and symbols ... **2**
4.1 Abbreviated terms ... 2
4.2 Symbols ... 2

5 Purpose and classification of multivariate control charts ... **4**
5.1 Purpose and applying conditions for multivariate control charts ... 4
5.2 Classification of multivariate control charts ... 5

6 Multivariate control charts with unweighted averages for mean shift ... **6**
6.1 General ... 6
6.2 Control charts for the process mean (n>1) ... 7
6.2.1 χ^2 control chart when pre-specified parameter values are known ... 7
6.2.2 T^2 control chart when pre-specified parameter values are unknown ... 8
6.3 Control charts for the process mean (n=1) ... 8
6.3.1 χ^2 control chart when pre-specified parameter values are known ... 8
6.3.2 T^2 control chart when pre-specified parameter values are unknown ... 9
6.4 Summary and selection of multivariate control charts with unweighted averages for mean shifts ... 9
6.5 Test for assignable causes ... 10

7 Multivariate control charts with weighted averages for mean shifts ... **11**

8 Control charts for the process dispersion ... **12**

9 Interpretation of an out-of-control signal ... **13**

Annex A (informative) **Example of multivariate statistical process control** ... **14**

Annex B (informative) **Example of MEWMA control chart** ... **17**

Annex C (informative) **Estimation of μ and Σ** ... **23**

Bibliography ... **25**