# ISO/TR 11462-3:2020 (E)

## Guidelines for implementation of statistical process control (SPC) — Part 3: Reference data sets for SPC software validation

# Contents


Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions, and symbols and abbreviated terms

3.1 Terms and definitions
3.2 Symbols and abbreviated terms

4 Overview of the test examples

5 Reference data sets description and evaluation

5.1 Test data set 1
5.1.1 Test data set 1 information
5.1.2 Test data set 1 results
5.1.2.1 List of sample statistics
5.1.2.2 $\bar{x}$ chart
5.1.2.3 X chart
5.1.2.4 $\tilde{x}$ chart
5.1.2.5 s chart
5.1.2.6 R chart
5.1.2.7 Moving range chart
5.1.2.8 Process capability
5.2 Test data set 2
5.2.1 Test data set 2 information
5.2.2 Test data set 2 results
5.2.2.1 List of sample statistics
5.2.2.2 $\bar{x}$ chart
5.2.2.3 X chart
5.2.2.4 $\tilde{x}$ chart
5.2.2.5 s chart
5.2.2.6 R chart
5.2.2.7 Moving range chart
5.2.2.8 Process capability
5.3 Test data set 3
5.3.1 Test data set 3 information
5.3.2 Test data set 3 results
5.3.2.1 List of sample statistics
5.3.2.2 $\bar{x}$ - chart
5.3.2.3 X chart
5.3.2.4 $\tilde{x}$ chart
5.3.2.5 s chart
5.3.2.6 R chart
5.3.2.7 Moving range chart
5.3.2.8 Process capability
5.4 Test data set 4
5.4.1 Test data set 4 information
5.4.2 Test data set 4 results
5.4.2.1 List of sample statistics
5.4.2.2 $\bar{x}$ chart

5.4.2.3 X chart
5.4.2.4 $x\tilde{}$ – chart
5.4.2.5 s chart
5.4.2.6 R chart
5.4.2.7 Moving range chart
5.4.2.8 Process capability
5.5 Test data set 5
5.5.1 Test data set 5 information
5.5.2 Test data set 5 results
5.5.2.1 List of sample statistics
5.5.2.2 $\bar{x}$ chart
5.5.2.3 X chart
5.5.2.4 $x\tilde{}$ chart
5.5.2.5 s chart
5.5.2.6 R chart
5.5.2.7 Moving range chart
5.5.2.8 Process capability
5.6 Test data set 6
5.6.1 Test data set 6 information
5.6.2 Test data set 6 results
5.6.2.1 List of sample statistics
5.6.2.2 $\bar{x}$ chart
5.6.2.3 X chart
5.6.2.4 $x\tilde{}$ chart
5.6.2.5 s chart
5.6.2.6 R chart
5.6.2.7 Moving range chart
5.6.2.8 Process capability
5.7 Test data set 7
5.7.1 Test data set 7 information
5.7.2 Test data set 7 results
5.7.2.1 List of sample statistics
5.7.2.2 $\bar{x}$ chart
5.7.2.3 X chart
5.7.2.4 $x\tilde{}$ chart
5.7.2.5 s chart
5.7.2.6 R chart
5.7.2.7 Moving range chart
5.7.2.8 Process capability
5.8 Test data set 8
5.8.1 Test data set 8 information
5.8.2 Test data set 8 results
5.8.2.1 List of sample statistics
5.8.2.2 $\bar{x}$ chart
5.8.2.3 X chart
5.8.2.4 $x\tilde{}$ chart
5.8.2.5 s chart
5.8.2.6 R chart
5.8.2.7 Moving range chart
5.8.2.8 Process capability
5.9 Test data set 9
5.9.1 Test data set 9 information
5.9.2 Test data set 9 results
5.9.2.1 List of sample statistics
5.9.2.2 $\bar{x}$ chart
5.9.2.3 X chart
5.9.2.4 $x\tilde{}$ chart
5.9.2.5 s chart
5.9.2.6 R chart
5.9.2.7 Moving range chart
5.9.2.8 Process capability
5.10 Test data set 10
5.10.1 Test data set 10 information
5.10.2 Test data set 10 results

5.10.2.1 List of sample statistics
5.10.2.2 $\bar{x}$ chart
5.10.2.3 X chart
5.10.2.4 $\tilde{x}$ chart
5.10.2.5 s chart
5.10.2.6 R chart
5.10.2.7 Moving range chart
5.10.2.8 Process capability
5.11 Test data set 11
5.11.1 Test data set 11 information
5.11.2 Test data set 11 results
5.11.2.1 List of sample statistics
5.11.2.2 Grubbs tests for outliers
5.11.2.3 Bartlett test for homogeneity of variances
5.11.2.4 Fisher test for equal location
5.11.2.5 Process capability

Annex A (informative) Test data values

A.1 Test data sets 1-10
A.2 Test data set 11

Page count: 129