DIN ISO 7870-2:2021-04 (E)

Control charts - Part 2: Shewhart control charts (ISO 7870-2:2013)

Contents

Page

National foreword 4

National Annex NA (informative) Bibliography 6

Foreword 7

Introduction 8

1 Scope 9

2 Normative references 9

3 Terms,definitionsandsymbols 9
3.1 General 9
3.2 Symbols 9

4 Nature of Shewhart control charts 11

5 Typesofcontrolcharts 13
5.1 Control charts where no pre-specified values are given 13
5.2 Control charts with respect to given pre-specified values 14
5.3 Types of variables and attributes control charts 14

6 Variablescontrolcharts 15
6.1 Mean (X) chart and range (R) chart or mean (X) chart and standard deviation (s) chart ..16
6.2 Control chart for individuals (X) and control chart for moving ranges (Rm) 17
6.3 Control charts for medians (X) 18

7 Controlprocedureandinterpretationforvariablescontrolcharts 19
7.1 Collect preliminary data 19
7.2 Examine the s (or R) chart 19
7.3 Remove assignable causes and revise the chart 19
7.4 Examine the X chart 20
7.5 Ongoing monitoring of process 20

8 Patterntestsforassignablecausesofvariation 20

9 Processcontrol,processcapability,andprocessimprovement 21

10 Attributescontrolcharts 23

11 Preliminaryconsiderationsbeforestartingacontrolchart 25
11.1 Choice of critical to quality (CTQ) characteristics describing the process to control 25
11.2 Analysis of the process 25
11.3 Choice of rational subgroups 25
11.4 Frequency and size of subgroups 26
11.5 Preliminary data collection 26
11.6 Out of control action plan 26

12 Steps in the construction of control charts 26
12.1 Determine data collection strategy 27
12.2 Data collection and computation 28

12.3 Plotting X chart and R chart 28

DIN ISO 7870-2:2021-04 13 Caution with Shewhart control charts 28

13.1 General caution 29
13.2 Correlated data 30
13.3 Use of alternative rule to the three-sigma rule 30

Annex A (informative) Illustrative examples 32

Annex B (informative)Practicalnoticesonthepatterntestsforassignablecausesofvariation 50

Bibliography 52