ISO 2859-4:2002-08 (E)

Sampling procedures for inspection by attributes - Part 4: Procedures for assessment of declared quality levels

Contents

Page

1 Scope 1

2 Normative references 2

3 Terms, definitions, symbols and abbreviations 2

4 Principles 3

5 Declared quality level (DQL) 4

6 Sampling plans 4

7 Operating a sampling plan 6

8 Further information 7

Annex A Examples of use of the procedures 11

A.1 Example 1 11
A.2 Example 2 11
A.3 Example 3 11