ISO 3951-2:2006-04 (E)

Samplin g procedures for inspection by variables - Part 2: General specification for single sampling plans indexed by acceptance quality limit (AQL) for lot-by-lot inspection of independent quality characteristics

Contents

Page

Foreword v

Introduction vii

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols 6

5 Acceptance quality limit (AQL) 8

6 Switching rules for normal, tightened and reduced inspection 9

8 Consumer protection 12

9 Planning 13

10 Choice between variables and attributes 13

11 Choice between the "s" and "" methods 14

12 Choice of inspection level and AQL 14

13 Choice of sampling scheme 15

14 Preliminary operations 17

15 Standard univariate "s" method procedures 17

16 Standard multivariate "s" method procedures for independent quality characteristics 26

17 Standard univariate "" method procedures 28

18 Standard multivariate "" method procedures for independent quality characteristics 31

19 Standard multivariate combined "s" and "" method procedures for independent quality characteristics 32

20 Procedure during continuing inspection 34

21 Normality and outliers 34

22 Records 34

23 Operation of switching rules 35

24 Discontinuation and resumption of inspection 36

25 Switching between the "s" and "" methods 36

Annex A (normative) Tables for determining the appropriate sample size 37

Annex B (normative) Form k single sampling plans for the "s" method 39

Annex C (normative) Form k single sampling plans for the "" method 43

Annex D (normative) Values of fs for maximum sample standard deviation (MSSD) 47

Annex E (normative) Values of f process standard deviation 51

Annex F (normative) Estimating the process fraction nonconforming for sample size 3: "s" method 54

Annex G (normative) Form p* single sample plans 57

Annex H (normative) Values of cU for upper control limit on the sample standard deviation 61

Annex I (normative) Supplementary acceptability constants for qualifying towards reduced inspection 62

Annex J (normative) Procedures for obtaining s or 63

Annex K (normative) Estimating the process fraction nonconforming 65

Annex L (informative) Consumer's risk qualities 69

Annex M (informative) Producer's risks 74

Annex N (informative) Operating characteristics for the "" method 79

Bibliography 80