ISO 16145-4:2013-02 (E)

Ships and marine technology - Protective coatings and inspection method - Part 4: Automated measuring method for the total amount of water-soluble salts

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle of measurement 2

5 General requirements 2
5.1 Standard solutions 2
5.2 Composition of detector 2
5.3 Conductivity meter 2
5.4 Water 2

6 Measurement procedure 2
6.1 General 2
6.2 Blank test 3
6.3 General requirements of extraction of salts from the steel surface 3
6.4 Conductivity measurement 3
6.5 Cleaning of the detector 3

7 Expression of results 3
7.1 Measurement with direct reading from instrument 3
7.2 Calculation results 3

Bibliography 5