ISO/TR 18931:2001-06 (E)

Imaging materials - Recommendations for humidity measurement and control

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Terms and definitions 1

3 Moisture content of gases 2

4 Measuring systems 2

5 Sensor location 5

6 Recommendations 5

Annex A Importance of relative humidity 6

Annex B Humidity control in storage areas 7

Bibliography 8