ISO 17295:2023-01 (E)

Additive manufacturing - General principles - Part positioning, coordinates and orientation

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Machine coordinate systems for additive manufacturing machines with different build directions 1
4.1 General 1
4.2 Machine coordinate system for additive manufacturing machines with upwards Z-positive build direction 1
4.3 Machine coordinate system for additive manufacturing machines with downwards Z-positive build direction 2

5 Rule for positive direction of axes of rotation 3

6 Bounding box 3

7 Initial build orientation 4

8 Orthogonal orientation notation 6
8.1 General 6
8.2 Bilateral symmetry 7
8.3 Abbreviation of orthogonal orientation notation 8

9 Representation of part location and initial build orientation 8

10 Representation of part location and reorientation 9

Bibliography 12