DIN EN 16806-1:2016-07 (E)

Textiles and textile products - Textiles containing phase change materials (PCM) - Part 1: Determinatio n of the heat storage and release capacity

Contents

Page

European foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Principle of test 5

5 Test equipment, reagents and materials 5

6 Test specimens 5

7 DSC test procedure 7

8 Calculation of test results 7

9 Test report 8

Bibliography 10