

# ISO 7503-2:2016-01 (E)

## Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 2: Test method using wipe-test samples

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions, symbols and abbreviations .....	2
3.1	Terms and definitions .....	2
3.2	Symbols and abbreviated terms .....	3
4	Sources of surface contamination .....	3
5	Objectives of the surface contamination evaluation .....	4
6	Strategy .....	4
7	Methods for evaluating surface contamination .....	4
8	Wipe test material .....	5
9	Instrumentation .....	5
9.1	General .....	5
9.2	Liquid scintillation counters .....	6
10	Calibration .....	6
10.1	Calibration of installed instruments .....	6
10.2	Calibration of portable instruments .....	6
11	Guidelines on wipe test sampling .....	6
11.1	General .....	6
11.2	Guidelines on sampling removable tritium contamination .....	7
12	Measurement procedure .....	7
13	Evaluation of measurement data .....	8
13.1	Calculation of the activity per unit area for measurement results of installed instruments	8
	13.2 Calculation of the activity per unit area for measurement results of portable instruments	9
	13.3 Application of ISO 11929 .....	9
14	Wipe test uncertainties .....	9
15	Test report .....	9
Bibliography .....		11