

ISO 7503-2:2016-01 (E)

Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 2: Test method using wipe-test samples

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions, symbols and abbreviations	2
3.1	Terms and definitions	2
3.2	Symbols and abbreviated terms	3
4	Sources of surface contamination	3
5	Objectives of the surface contamination evaluation	4
6	Strategy	4
7	Methods for evaluating surface contamination	4
8	Wipe test material	5
9	Instrumentation	5
9.1	General	5
9.2	Liquid scintillation counters	6
10	Calibration	6
10.1	Calibration of installed instruments	6
10.2	Calibration of portable instruments	6
11	Guidelines on wipe test sampling	6
11.1	General	6
11.2	Guidelines on sampling removable tritium contamination	7
12	Measurement procedure	7
13	Evaluation of measurement data	8
13.1	Calculation of the activity per unit area for measurement results of installed instruments	8
	13.2 Calculation of the activity per unit area for measurement results of portable instruments	9
	13.3 Application of ISO 11929	9
14	Wipe test uncertainties	9
15	Test report	9
Bibliography		11