

ISO 7503-1:2016-01 (E)

Measurement of radioactivity - Measurement and evaluation of surface contamination - Part 1: General principles

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions, symbols and abbreviations	2
3.1	Terms and definitions	2
3.2	Symbols and abbreviated terms	3
4	Objectives of surface contamination measurements	4
4.1	General	4
4.2	National and international regulations	4
4.3	Definition of the measuring programme	4
5	Direct and indirect methods of assessing surface contamination	5
5.1	General	5
5.2	Direct method	6
5.3	Indirect method (wipe tests)	6
5.4	Wipe test uncertainties	6
6	Radionuclide identification and spectral analysis	6
7	Monitoring instruments	7
7.1	Selection of monitors	7
7.2	Introduction to the calibration of surface contamination instruments for direct measurement	7
7.3	Tests before first use (TBFU)	8
7.4	Periodic calibration	9
7.5	Function check	9
8	Estimation of surface contamination monitor response and calibration factors	9
8.1	General	9
8.2	Relationship between surface emission rate and activity	10
9	Evaluation of measurement data	12
10	Uncertainties	12
10.1	General	12
10.2	Assessment of uncertainty in the calibration factor	12
10.3	Assessment of uncertainty in the measurement	13
10.4	Wipe test uncertainties	14
11	Test report for a surface contamination instrument	14
Annex A (informative) Calibration of surface contamination instruments		16
Annex B (informative) Example of surface contamination estimation		21

Annex C (informative) Calibration of dose rate measuring instruments	23
Bibliography	25