ISO 20042:2019 (E)

Measurement of radioactivity — Gamma-ray emitting radionuclides — Generic test method using gamma-ray spectrometry

Contents

Foreword

Introduction

- 1 Scope
- 2 Normative references
- 3 Terms and definitions
- 4 Symbols and units
- 5 Principle
 - 5.1 General
 - 5.2 Summing method
 - 5.3 Fitting method
- 6 Validating measurements by gamma-ray spectrometry
 - 6.1 General
 - 6.2 Step 1: customer requirements
 - 6.3 Step 2: technical requirements
 - 6.4 Step 3: detailed design
 - 6.5 Step 4: installation
 - 6.6 Step 5: validation studies
 - 6.7 Step 6: robustness
 - 6.8 Step 7: operation and maintenance
- 7 Nuclear decay data
 - 7.1 Recommended nuclear decay data
 - 7.2 Selection of gamma-ray photopeaks for inclusion in spectrum analysis libraries
 - 7.3 Decay chains

8 Detector energy and efficiency calibration

- 8.1 Energy calibration
- 8.2 Efficiency calibration
- 8.3 Source(s) for energy calibration
- 8.4 Reference source(s) for efficiency calibration
- 8.4.1 General
- 8.4.2 Reference sources for laboratory systems
- 8.4.3 Reference sources used with numerical methods
- 9 Sample container

10 Procedure

- 10.1 Sample measuring procedure
- 10.1.1 Sampling
- 10.1.2 Sample preparation
- 10.1.3 Loading the sample container
- 10.1.4 Recording the sample spectrum
- 10.2 Analysis of the spectrum
- 10.2.1 Procedure for laboratory-based measuring systems
- 10.2.2 Background corrections

11 Expression of results

- 11.1 Calculation of activity and activity per kg (or m3) of sample
- 11.2 Determination of the characteristic limits
- 12 Test report

Annex A (informative) Quality assurance and quality control program

- A.1 General
- A.2 Influencing variables
- A.3 Instrument verification
- A.4 Method verification
- A.5 Quality assurance plan
- A.6 Energy calibration
- A.7 Efficiency calibration
- A.8 Full width half maximum
- A.9 Background
- A.10 Staff training and assessment
- A.11 Documentation

Annex B (informative) Corrections to the analysis process

- B.1 General
- B.2 Sample geometry
- B.3 Composition and density correction (internal absorption)
- B.4 Pulse pile-up and dead time
- B.5 True coincidence summing correction
- Annex C (informative) Uncertainty budget
 - C.1 General
 - C.2 Uncertainty components
 - C.3 Implementation of uncertainty budget
- Annex D (informative) Detector types
- Annex E (informative) Example: Calculation of 137Cs activity content and characteristic limits in an aqueous sample
 - E.1 Principle
 - E.2 Measurement
 - E.3 Calculation of activity content
 - E.4 Characteristic limits
 - E.5 Decision threshold
 - E.6 Detection limit
- Annex F (informative) Example: Simulating correction factors for sample positioning, geometry, matrix, density and true summing
 - F.1 Introduction
 - F.2 Effect of sample-to-detector distance (H1)
 - F.3 Effect of off-axis displacement (PA)
 - F.4 Effect of fill height (HS)
 - F.5 Detection efficiency for different layer of the sample
 - F.6 Effect of density (RO) and matrix (MA)
 - F.7 Effect of true coincidence summing as a function of sample to detector distance (H1)
 - F.8 Summary

Page count: 50