

ISO/TR 18336:2016-02 (E)

Guidelines for good XRF laboratory practice for the iron ore industry

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Reagents	1
3	Apparatus	2
4	Fused glass beads	5
4.1	General	5
4.2	Storage	5
4.3	Disc making precision	5
4.4	Bead distortion (curvature and flatness)	6
5	Quality control	6
5.1	Selection of QC samples and frequency of preparation	6
5.2	Analysis of QC and analytical samples	7
5.3	Control charts	7
5.4	Participation in proficiency test programs	8
Annex A (informative) Results for flux loss on ignition testing		9
Annex B (informative) Procedure to check disc making precision		10
Annex C (informative) Method to determine relationship between height and concentration		11
Annex D (informative) Production of a height adjustable cup		12
Annex E (informative) Bead measurement apparatus		13
Annex F (informative) Flow sheet for fused bead quality		14
Annex G (informative) Microsoft Excel program for calculating disc precision		15
Annex H (informative) Data input screen for calculating disc precision		19
Annex I (informative) Loss of accuracy with no loss of precision		20
Annex J (informative) Loss of accuracy with loss of precision		22
Annex K (informative) Loss of accuracy and precision -- Loss of bead making precision		23
Annex L (informative) Results for spectrometer precision test		25
Annex M (informative) Drift correction		26
Bibliography		27