

ISO5418-2 :2006-12 (E)

Iron ores_ - Determination of copper_ - Part_2: Flame atomic absorption spectrometric method

Contents

Page

Foreword.....	iv
1 Scope	1
2 Normative references	1
3 Principle	1
4 Reagents	2
5 Apparatus	3
6 Sampling and samples	3
6.1 Laboratory sample	3
6.2 Preparation of predried test samples	4
7 Procedure	4
7.1 Number of determinations	4
7.2 Blank test and check test.....	4
7.3 Test portion	4
7.4 Determination.....	4
7.4.1 Decomposition of the test portion	4
7.4.2 Treatment of the solution.....	5
7.4.3 Preparation of the set of calibration solutions	5
7.4.4 Adjustment of atomic absorption spectrometer	5
7.4.5 Atomic absorption measurements.....	6
8 Expression of results	6
8.1 Calculation of mass fraction of copper	6
8.2 General treatment of results.....	6
8.2.1 Repeatability and permissible tolerance	6
8.2.2 Determination of analytical result	7
8.2.3 Between-laboratories precision	7
8.2.4 Check for trueness	8
8.2.5 Calculation of final result.....	8
8.3 Oxide factor	9
9 Test report	9
Annex A (normative) Flowsheet of the procedure for the acceptance of analytical values for test samples.....	10
Annex B (informative) Derivation of repeatability and permissible tolerance equations	11
Annex C (informative) Precision data obtained by international analytical trials	12