

# ISO 9370:2009-07 (E)

## Plastics - Instrumental determination of radiant exposure in weathering tests - General guidance and basic test method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Significance and use .....</b>	<b>6</b>
4.1	General considerations .....	6
4.2	Natural weathering -- Fixed-angle or equatorial-mount exposure .....	6
4.3	Accelerated natural weathering -- Solar-concentrating exposures using Fresnel- reflecting concentrators .....	7
4.4	Artificial accelerated weathering and artificial accelerated irradiation .....	7
<b>5</b>	<b>Apparatus .....</b>	<b>8</b>
5.1	General .....	8
5.2	Non-selective radiometers (see Table 1) .....	9
5.3	Selective (UV) radiometers (see Table 2) .....	10
5.4	Recorders and data loggers .....	10
<b>6</b>	<b>Calibration .....</b>	<b>10</b>
6.1	General .....	10
6.2	Reference and field radiometers .....	11
6.3	Selective reference radiometers .....	11
6.4	Selective field radiometers .....	12
6.5	Other requirements .....	12
<b>7</b>	<b>Procedure .....</b>	<b>12</b>
7.1	Natural weathering -- Fixed-angle or equatorial-mount exposure .....	12
7.2	Accelerated natural weathering -- Solar concentrating exposures using Fresnel- reflecting concentrators .....	12
7.3	Artificial accelerated weathering or artificial accelerated irradiation .....	13
<b>8</b>	<b>Exposure report .....</b>	<b>13</b>
<b>Annex A (informative) Comparison of typical wide-band UV radiometers .....</b>		<b>14</b>
<b>Bibliography .....</b>		<b>15</b>