

ISO 1183-1:2012-05 (E)

Plastics - Methods for determining the density of non-cellular plastics - Part 1: Immersion method, liquid pycnometer method and titration method

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Conditioning	2
5	Methods	2
5.1	Method A -- Immersion method	2
5.2	Method B -- Liquid pycnometer method	4
5.3	Method C -- Titration method	5
6	Correction for buoyancy in air	6
7	Test report	7
Annex A (informative) Liquid systems suitable for use in Method C		8
Annex B (informative) Correction for buoyancy in air		9
Bibliography		10