

ISO 11357-2:2013-05 (E)

Plastics - Differential scanning calorimetry (DSC) - Part 2: Determination of glass transition temperature and glass transition step height

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Apparatus and materials	2
6	Test specimens	2
7	Test conditions and specimen conditioning	2
8	Calibration	2
9	Procedure	2
9.1	Setting up the apparatus	2
9.2	Loading the test specimen into the crucible	2
9.3	Insertion of crucibles	2
9.4	Temperature scan	2
10	Expression of results	3
10.1	Determination of glass transition temperatures	3
10.2	Determination of glass transition step height	5
11	Precision	5
12	Test report	5
Bibliography		6