

DIN EN 13999-1:2014-03 (E)

Adhesives - Short term method for measuring the emission properties of low-solvent or solvent-free adhesives after application - Part 1: General procedure

Contents		Page
Foreword		3
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Principle	6
5	Apparatus	7
5.1	General	7
5.2	Support	7
5.3	Adhesive coating device	7
5.4	Emission test chamber	7
5.5	Air supply and mixing facilities	8
5.6	Air sampling devices	9
5.7	Devices for desorption and analysis	9
6	Adhesive sample	9
6.1	General	9
6.2	Pre-conditioning	9
6.3	Preparation of a test specimen	9
7	Procedure	10
7.1	Number of determinations	10
7.2	Preconditioning of the test chamber	10
7.3	Operation of the test chamber	10
7.4	Starting of the test	10
7.5	Sampling and analysis of emitted substances	10
8	Expression of results	11
8.1	Calculations	11
8.2	Carcinogenic and sensitizing compounds concentration	11
8.3	Volatile organic compounds	11
8.3.1	General	11
8.3.2	Determination of the specific emission rate at the sampling times	11
8.3.3	Determination of the empirical parameters a and b	12
9	Test report	13
Annex A (normative) Carcinogenic and sensitizing substances		14
Bibliography		15