

# DIN EN ISO 4892-1:2016-10 (E)

## Plastics - Methods of exposure to laboratory light sources - Part 1: General guidance (ISO 4892-1:2016)

---

<b>Contents</b>		Page
<b>European foreword</b> .....		<b>3</b>
<b>Foreword</b> .....		<b>4</b>
<b>Introduction</b> .....		<b>5</b>
<b>1 Scope</b> .....		<b>6</b>
<b>2 Normative references</b> .....		<b>6</b>
<b>3 Terms and definitions</b> .....		<b>7</b>
<b>4 Principle</b> .....		<b>7</b>
4.1 General .....		7
4.2 Significance .....		8
4.3 Use of accelerated tests with laboratory light sources .....		9
<b>5 Requirements for laboratory exposure devices</b> .....		<b>10</b>
5.1 Irradiance .....		10
5.2 Temperature .....		11
5.3 Humidity and wetting .....		13
5.4 Other requirements for the exposure device .....		14
<b>6 Test specimens</b> .....		<b>15</b>
6.1 Form, shape and preparation .....		15
6.2 Number of test specimens .....		16
6.3 Storage and conditioning .....		16
<b>7 Test conditions and procedure</b> .....		<b>16</b>
7.1 Set points for exposure conditions .....		16
7.2 Property measurements on test specimens .....		17
<b>8 Periods of exposure and evaluation of test results</b> .....		<b>18</b>
8.1 General .....		18
8.2 Use of control materials .....		18
8.3 Use of results in specifications .....		18
<b>9 Test report</b> .....		<b>19</b>
<b>Annex A (normative) Procedures for measuring the irradiance uniformity in the specimen exposure area</b> .....		<b>21</b>
<b>Annex B (informative) Factors that decrease the degree of correlation between artificial accelerated weathering or artificial accelerated irradiation exposures and actual-use exposures</b> .....		<b>24</b>
<b>Annex C (informative) Solar spectral irradiance standards</b> .....		<b>27</b>
<b>Bibliography</b> .....		<b>29</b>