

DIN EN ISO 4892-1:2016-10 (E)

Plastics - Methods of exposure to laboratory light sources - Part 1: General guidance (ISO 4892-1:2016)

Contents

	Page
European foreword	3
Foreword	4
Introduction	5
1 Scope	6
2 Normative references	6
3 Terms and definitions	7
4 Principle	7
4.1 General	7
4.2 Significance	8
4.3 Use of accelerated tests with laboratory light sources	9
5 Requirements for laboratory exposure devices	10
5.1 Irradiance	10
5.2 Temperature	11
5.3 Humidity and wetting	13
5.4 Other requirements for the exposure device	14
6 Test specimens	15
6.1 Form, shape and preparation	15
6.2 Number of test specimens	16
6.3 Storage and conditioning	16
7 Test conditions and procedure	16
7.1 Set points for exposure conditions	16
7.2 Property measurements on test specimens	17
8 Periods of exposure and evaluation of test results	18
8.1 General	18
8.2 Use of control materials	18
8.3 Use of results in specifications	18
9 Test report	19
Annex A (normative) Procedures for measuring the irradiance uniformity in the specimen exposure area	21
Annex B (informative) Factors that decrease the degree of correlation between artificial accelerated weathering or artificial accelerated irradiation exposures and actual-use exposures	24
Annex C (informative) Solar spectral irradiance standards	27
Bibliography	29