

ISO 1183-3:1999-09 (E)

Plastics - Methods for determining the density of non-cellular plastics - Part 3: Gas pyknometer method

Contents		Page
1	Scope	1
2	Terms, definitions, symbols, units and abbreviated terms	1
3	Principle	2
4	Apparatus and materials	3
5	Test specimens	3
6	Calibration	3
7	Procedure and calculation	4
8	Precision	4
9	Test report	4
Annex A (informative) Two-chamber pressure-measuring pyknometer		6