

# ISO/TS 19022:2016-02 (E)

## Plastics - Method of controlled acceleration of laboratory weathering by increased irradiance

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	2
5	Principle .....	2
6	Apparatus .....	2
6.1	General .....	2
6.2	Test chamber .....	2
6.3	Laboratory radiation source .....	3
6.3.1	General .....	3
6.3.2	Spectral irradiance .....	3
6.3.3	Irradiance uniformity .....	3
6.4	Radiometer .....	4
6.5	Test chamber temperature and relative humidity .....	4
6.6	Black-standard/black-panel thermometer .....	4
6.7	Wetting and humidity-control equipment .....	4
6.7.1	General .....	4
6.7.2	Relative-humidity control equipment .....	4
6.7.3	Spray system .....	4
6.8	Specimen holders .....	4
6.9	Apparatus to assess changes in properties .....	5
7	Test specimens .....	5
8	Test method .....	5
9	Exposure conditions .....	6
9.1	Radiation .....	6
9.2	Temperature .....	6
9.2.1	Black-standard and black-panel temperature .....	6
9.2.2	Chamber air temperature .....	6
9.2.3	Specimen surface temperature .....	6
9.3	Humidity of chamber air .....	7
9.3.1	Relative humidity of chamber air .....	7
9.3.2	Spray cycle .....	7
10	Procedure .....	7
10.1	General .....	7
10.2	Mounting the test specimens .....	7
10.3	Exposure .....	7
10.4	Measurement of radiant exposure .....	8
10.5	Determination of changes in properties after exposure .....	8

11	Test report .....	8
	Annex A (informative) Principle of reciprocity .....	9
	Bibliography .....	10