

ISO/TS 19022:2016-02 (E)

Plastics - Method of controlled acceleration of laboratory weathering by increased irradiance

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms	2
5 Principle	2
6 Apparatus	2
6.1 General	2
6.2 Test chamber	2
6.3 Laboratory radiation source	3
6.3.1 General	3
6.3.2 Spectral irradiance	3
6.3.3 Irradiance uniformity	3
6.4 Radiometer	4
6.5 Test chamber temperature and relative humidity	4
6.6 Black-standard/black-panel thermometer	4
6.7 Wetting and humidity-control equipment	4
6.7.1 General	4
6.7.2 Relative-humidity control equipment	4
6.7.3 Spray system	4
6.8 Specimen holders	4
6.9 Apparatus to assess changes in properties	5
7 Test specimens	5
8 Test method	5
9 Exposure conditions	6
9.1 Radiation	6
9.2 Temperature	6
9.2.1 Black-standard and black-panel temperature	6
9.2.2 Chamber air temperature	6
9.2.3 Specimen surface temperature	6
9.3 Humidity of chamber air	7
9.3.1 Relative humidity of chamber air	7
9.3.2 Spray cycle	7
10 Procedure	7
10.1 General	7
10.2 Mounting the test specimens	7
10.3 Exposure	7
10.4 Measurement of radiant exposure	8
10.5 Determination of changes in properties after exposure	8

11	Test report	8
	Annex A (informative) Principle of reciprocity	9
	Bibliography	10