

# ISO 23976:2021-02 (E)

## Plastics - Fast differential scanning calorimetry (FSC) - Chip calorimetry

---

<b>Contents</b>		<b>Page</b>
	Foreword .....	v
	Introduction .....	vi
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>2</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>2</b>
<b>4</b>	<b>Principle</b> .....	<b>3</b>
<b>5</b>	<b>Apparatus</b> .....	<b>4</b>
	5.1 Chip calorimeter .....	4
	5.2 Microscope .....	5
	5.3 Tools for sample preparation .....	5
	5.4 Calibration materials .....	5
	5.5 Measuring atmosphere .....	5
<b>6</b>	<b>Specimens</b> .....	<b>5</b>
<b>7</b>	<b>Test conditions and specimen conditioning</b> .....	<b>6</b>
	7.1 Test conditions .....	6
	7.2 Conditioning of specimens .....	6
<b>8</b>	<b>Calibration</b> .....	<b>6</b>
	8.1 Chip calorimeter performance .....	6
	8.2 Temperature calibration <sup>[14],[17]</sup> .....	8
	8.2.1 General .....	8
	8.2.2 Correction for thermal lag due to scan rate .....	9
	8.2.3 Correction for thermal lag due to sample mass .....	10
	8.2.4 Correction of measured temperature extrapolated to zero heating rate .....	10
	8.3 Symmetry of temperature calibration <sup>[14],[17],[21]</sup> .....	12
	8.3.1 General .....	12
	8.3.2 Procedure .....	12
	8.4 Calibration of heat and heat flow rate .....	13
<b>9</b>	<b>Specimen measurement procedure</b> .....	<b>14</b>
	9.1 Preparation of apparatus .....	14
	9.1.1 Starting the instrument .....	14
	9.1.2 Purge gas .....	14
	9.1.3 Preparation of sensor .....	14
	9.1.4 Blank correction for heat loss <sup>[23]</sup> .....	14
	9.2 Placement of specimens on the sensor .....	15
	9.3 Performance of measurements .....	16
	9.3.1 General .....	16
	9.3.2 Running the instrument .....	17
	9.3.3 Reuse of chip sensor .....	17
	9.3.4 Evaluation of results .....	17
<b>10</b>	<b>Investigation of physical-chemical effects</b> .....	<b>17</b>
	10.1 General .....	17
	10.2 First Order phase transitions .....	17
	10.3 Chemical reactions .....	17
	10.4 Glass transitions .....	18

<b>11</b>	<b>Determination of heat capacity<sup>[24]</sup></b> .....	<b>18</b>
<b>12</b>	<b>Determination of specimen mass<sup>[14],[23]</sup></b> .....	<b>20</b>
12.1	General.....	20
12.2	Determination of specimen mass based on specific heat capacity of material.....	21
12.3	Determination of specimen mass based on specific heat capacity change at glass transition.....	21
12.4	Determination of specimen mass based on specific enthalpy of fusion.....	22
12.5	Determination of specimen mass based on specimen dimensions and density.....	23
12.6	Use of FSC reference specimens.....	23
12.7	Criteria for selection of correct specimen mass.....	23
	12.7.1 High specimen mass.....	23
	12.7.2 Low specimen mass.....	24
<b>13</b>	<b>Precision and bias</b> .....	<b>24</b>
<b>14</b>	<b>Test report</b> .....	<b>25</b>
	<b>Bibliography</b> .....	<b>26</b>