

ISO 4765:2022-04 (E)

Chemically- induced ultra-weak photon emission (UPE) - Measurement as an analysis method of degradation of polymeric material

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Measurement principle and its limitations	2
5	Sample	2
6	UPE measuring apparatus	3
6.1	Composition of UPE apparatus body	3
6.2	Composition of sample chamber	3
6.3	Installation environment for UPE apparatus	4
6.4	Sensitivity check	4
7	Measurement method	5
7.1	UPE apparatus preparation	5
7.2	Confirmation of normal operation of UPE apparatus	5
7.3	Measurement procedure	5
7.3.1	Setting of measurement condition	5
7.3.2	Measurement of background	6
7.3.3	Sample measurement	6
8	Display of measurement results	7
8.1	General	7
8.2	Measurement in inert gas atmosphere	7
8.3	Measurement in oxidation accelerating atmosphere	8
9	Test report	10
Annex A (informative) Detection of oxidation deterioration by UPE measurement		11
Annex B (informative) Examples of time courses of UPE of thermally oxidized polypropylene (PP) for isothermal and non-isothermal measurement		16
Annex C (informative) Example of measurements of oxidation deterioration degree of thermally oxidized polyethylene (PE)		18
Annex D (informative) Example evaluation of oxidation induction time (OIT)		20
Annex E (informative) Example of UPE of PP oxidized by accelerated weathering test		22
Bibliography		26