

# ISO 2114:2000-08 (E)

## Plastics (polyester resins) and paints and varnishes (binders) - Determination of partial acid value and total acid value

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Principle</b> .....	<b>2</b>
<b>5</b>	<b>Reagents</b> .....	<b>2</b>
<b>6</b>	<b>Apparatus</b> .....	<b>3</b>
<b>7</b>	<b>Procedure</b> .....	<b>4</b>
<b>8</b>	<b>Calculation and expression of results</b> .....	<b>6</b>
<b>9</b>	<b>Precision</b> .....	<b>7</b>
<b>10</b>	<b>Test report</b> .....	<b>8</b>
<b>Annex A (informative) Checking the concentration of the standard potassium hydroxide solution</b> .....		<b>9</b>