

ISO 2114:2000-08 (E)

Plastics (polyester resins) and paints and varnishes (binders) - Determination of partial acid value and total acid value

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Reagents	2
6	Apparatus	3
7	Procedure	4
8	Calculation and expression of results	6
9	Precision	7
10	Test report	8
Annex A (informative) Checking the concentration of the standard potassium hydroxide solution		9