

ISO/TS 24110:2026-04 (E)

Plastics - Method of exposure to combined UV radiation and creep load

Contents

Page

Foreword.....	iv
Introduction.....	v
1 Scope.....	1
2 Normative references.....	1
3 Terms and definitions.....	1
4 Principle.....	2
5 Apparatus.....	2
5.1 General.....	2
5.2 Test device for combined exposure.....	2
5.3 Laboratory UV radiation source.....	2
5.3.1 General.....	2
5.3.2 Fluorescent UVA lamp.....	2
5.3.3 Fluorescent UVB lamp.....	2
5.3.4 Low pressure mercury UVC lamp.....	2
5.4 Radiometer.....	2
5.5 Black-panel/black-standard thermometer.....	2
5.6 Creep device.....	3
5.6.1 General.....	3
5.6.2 Loading system.....	3
5.6.3 Specimen grip.....	3
5.7 Assessment of changes in properties.....	3
6 Test specimens.....	3
7 Test conditions for combined exposure.....	3
8 Procedure.....	4
8.1 General.....	4
8.2 Mounting of the test specimen.....	4
8.3 Combined exposure.....	5
8.3.1 Conditioning.....	5
8.3.2 Preloading.....	5
8.3.3 Loading.....	5
8.3.4 UV exposure.....	5
8.4 Extension measurement schedule.....	5
8.5 Time measurement for creep.....	5
8.6 Measurement of radiant exposure.....	5
8.7 Determination of the changes in properties after exposure.....	5
9 Test report.....	5
Annex A (informative) Comparison of UV exposure and combined creep 10 %, 20 %, 30 % creep load based on tensile yield strength.....	7
Annex B (informative) Combined UV radiation and creep load test equipment.....	10