

# ISO 4892-4:2004-09 (E)

## Plastics - Methods of exposure to laboratory light sources - Part 4: Open-flame carbon-arc lamps

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Principle .....</b>	<b>1</b>
<b>4</b>	<b>Apparatus .....</b>	<b>2</b>
<b>5</b>	<b>Test specimens .....</b>	<b>5</b>
<b>6</b>	<b>Test conditions .....</b>	<b>5</b>
<b>7</b>	<b>Procedure .....</b>	<b>6</b>
<b>8</b>	<b>Exposure report .....</b>	<b>7</b>