

# ISO 4892-2:2006-02 (E)

## Plastics - Methods of exposure to laboratory light sources - Part 2: Xenon-arc lamps

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Principle .....	1
4	Apparatus .....	2
5	Test specimens .....	6
6	Exposure conditions .....	6
7	Procedure .....	8
8	Exposure report .....	8
Annex A (informative) Filtered xenon-arc radiation -- Spectral power distribution .....		9
Bibliography .....		10