

DIN EN 13999-1:2006-11 (E)

Adhesives - Short term method for measuring the emission properties of low-solvent or solvent-free adhesives after application - Part 1: General procedure

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	6
4	Principle	6
5	Apparatus	6
5.1	Support	6
5.2	Adhesive coating device	7
5.3	Emission test chamber	7
5.4	Air supply and mixing facilities	7
5.5	Air sampling devices	8
5.6	Devices for desorption and analysis	8
6	Adhesive sample	8
6.1	General	8
6.2	Pre-conditioning	8
6.3	Preparation of a test specimen	8
7	Procedure	9
7.1	Number of determinations	9
7.2	Preconditioning of the test chamber	9
7.3	Operation of the test chamber	9
7.4	Starting of the test	9
7.5	Sampling and analysis of emitted substances	9
8	Expression of results	10
8.1	Calculations	10
8.2	Carcinogenic and sensitising compounds concentration	10
8.3	Volatile organic compounds	10
8.3.1	General	10
8.3.2	Determination of the specific emission rate at the sampling times	11
8.3.3	Determination of the specific cumulative emission in the 24 h to 240 h interval	11
8.3.4	Determination of the empirical parameters a and b	12
9	Test report	13
Annex A (normative) Carcinogenic and sensitising substances		14
Annex B (informative) Theoretical background of the calculation method		15
B.1	Determination of the specific emission rate	15
B.2	Determination of the specific cumulative emission in the 24 h to 240 h interval	15
Bibliography		18