

# ISO 12745:2008-10 (E)

## Copper, lead and zinc ores and concentrates - Precision and bias of mass measurement techniques

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>General remarks</b> .....	<b>4</b>
4.1	Draft surveys .....	4
4.2	Belt scales .....	5
4.3	Weighbridges .....	5
4.4	Hopper scales .....	6
4.5	Gantry scales .....	6
4.6	Platform scales .....	7
<b>5</b>	<b>Certified weights</b> .....	<b>7</b>
<b>6</b>	<b>Methods of operation</b> .....	<b>8</b>
6.1	General .....	8
6.2	Draft surveys .....	8
6.3	Belt scales .....	12
6.4	Weighbridges .....	14
6.5	Hopper scales .....	16
6.6	Gantry scales .....	18
6.7	Platform scales .....	20
<b>Tables</b>		
<b>Annex A (informative)</b> .....		<b>22</b>
<b>Annex B (informative) Statistics</b> .....		<b>32</b>
<b>Annex C (informative) Draft surveys</b> .....		<b>41</b>
<b>Annex D (informative) Procedure for the testing of static scales</b> .....		<b>44</b>
<b>Bibliography</b> .....		<b>47</b>