

DIN EN 15622:2010-06 (E)

Copper and copper alloys - Determination of lead content - Flame atomic absorption spectrometric method (FAAS)

| Contents | | Page |
|--------------------|--|-------------|
| Foreword | | 3 |
| 1 | Scope | 4 |
| 2 | Normative references | 4 |
| 3 | Principle | 4 |
| 4 | Reagents | 4 |
| 5 | Apparatus | 5 |
| 6 | Sampling | 5 |
| 7 | Procedure | 5 |
| 7.1 | Preparation of the test portion solution | 5 |
| 7.1.1 | Test portion | 5 |
| 7.1.2 | Test portion solution | 5 |
| 7.1.3 | Lead mass fractions between 0,01 % and 0,15 % | 6 |
| 7.1.4 | Lead mass fractions between 0,1 % and 0,75 % | 6 |
| 7.1.5 | Lead mass fractions between 0,5 % and 5,0 % | 6 |
| 7.2 | Blank test | 6 |
| 7.3 | Check test | 6 |
| 7.4 | Establishment of the calibration curve | 6 |
| 7.4.1 | Preparation of the calibration solutions | 6 |
| 7.4.2 | Adjustment of the atomic absorption spectrometer | 8 |
| 7.4.3 | Spectrometric measurement | 8 |
| 7.4.4 | Calibration curve | 8 |
| 7.5 | Determination | 8 |
| 7.5.1 | General | 8 |
| 7.5.2 | Preliminary spectrometric measurement | 9 |
| 7.5.3 | Spectrometric measurements | 9 |
| 8 | Expression of results | 9 |
| 8.1 | Use of calibration curve | 9 |
| 8.2 | Use of bracketing method | 9 |
| 9 | Precision | 10 |
| 10 | Test report | 11 |
| Bibliography | | 12 |