

DIN EN 15915:2010-12 (E)

Copper and copper alloys - Determination of silver content - Flame atomic absorption spectrometric method (FAAS)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	6
6	Sampling	6
7	Procedure	6
7.1	Preparation of the test portion solution -- Method A	6
7.1.1	General	6
7.1.2	Test portion	6
7.1.3	Test portion solution	6
7.2	Blank test	6
7.3	Check test	6
7.4	Establishment of the calibration curve	7
7.4.1	Preparation of the calibration solutions	7
7.4.2	Adjustment of the atomic absorption spectrometer	8
7.4.3	Spectrometric measurement of the calibration solutions	8
7.4.4	Calibration curve	8
7.5	Determination	8
7.5.1	General	8
7.5.2	Preliminary spectrometric measurement	8
7.5.3	Spectrometric measurements	9
7.6	Preparation of the test portion solution -- Method B	9
7.6.1	General	9
7.6.2	Test portion	9
7.6.3	Test portion solution	9
7.7	Blank test	9
7.8	Check test	10
7.9	Establishment of the calibration curve	10
7.9.1	Preparation of the calibration solutions	10
7.9.2	Adjustment of the atomic absorption spectrometer	11
7.9.3	Spectrometric measurement of the calibration solutions	12
7.9.4	Calibration curve	12
7.10	Determination	12
7.10.1	General	12
7.10.2	Preliminary spectrometric measurement	12
7.10.3	Spectrometric measurement	12
8	Expression of results	12
8.1	Use of the calibration curve	12
8.2	Use of bracketing method	13
9	Precision	13
10	Test report	15
Bibliography		16