

# DIN EN 15915:2010-12 (E)

## Copper and copper alloys - Determination of silver content - Flame atomic absorption spectrometric method (FAAS)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Principle .....	4
4	Reagents .....	4
5	Apparatus .....	6
6	Sampling .....	6
7	Procedure .....	6
7.1	Preparation of the test portion solution -- Method A .....	6
7.1.1	General .....	6
7.1.2	Test portion .....	6
7.1.3	Test portion solution .....	6
7.2	Blank test .....	6
7.3	Check test .....	6
7.4	Establishment of the calibration curve .....	7
7.4.1	Preparation of the calibration solutions .....	7
7.4.2	Adjustment of the atomic absorption spectrometer .....	8
7.4.3	Spectrometric measurement of the calibration solutions .....	8
7.4.4	Calibration curve .....	8
7.5	Determination .....	8
7.5.1	General .....	8
7.5.2	Preliminary spectrometric measurement .....	8
7.5.3	Spectrometric measurements .....	9
7.6	Preparation of the test portion solution -- Method B .....	9
7.6.1	General .....	9
7.6.2	Test portion .....	9
7.6.3	Test portion solution .....	9
7.7	Blank test .....	9
7.8	Check test .....	10
7.9	Establishment of the calibration curve .....	10
7.9.1	Preparation of the calibration solutions .....	10
7.9.2	Adjustment of the atomic absorption spectrometer .....	11
7.9.3	Spectrometric measurement of the calibration solutions .....	12
7.9.4	Calibration curve .....	12
7.10	Determination .....	12
7.10.1	General .....	12
7.10.2	Preliminary spectrometric measurement .....	12
7.10.3	Spectrometric measurement .....	12
8	Expression of results .....	12
8.1	Use of the calibration curve .....	12
8.2	Use of bracketing method .....	13
9	Precision .....	13
10	Test report .....	15
Bibliography .....		16