

DIN EN 15916-2:2010-12 (E)

Copper and copper alloys - Determination of tellurium content - Part 2: Medium tellurium content - Flame atomic absorption spectrometric method (FAAS)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	5
6	Sampling	5
7	Procedure	5
7.1	Preparation of the test portion solution	5
7.2	Blank test	5
7.3	Check test	5
7.4	Establishment of the calibration curve	6
7.5	Determination	7
8	Expression of results	7
8.1	Use of calibration curve	7
8.2	Use of bracketing method	8
9	Precision	8
10	Test report	9
Bibliography		10