

DIN EN 15022-4:2012-01 (E)

Copper and copper alloys - Determination of tin content - Part 4: Medium tin content - Flame atomic absorption spectro metric method (FAAS)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Principle	4
4	Reagents	4
5	Apparatus	5
6	Sampling	5
7	Procedure	5
7.1	Preparation of the test portion solution	5
7.1.1	Test portion	5
7.1.2	Test portion solution	5
7.2	Blank test	5
7.3	Check test	5
7.4	Establishment of the calibration curve	6
7.4.1	Preparation of the calibration solutions	6
7.4.2	Adjustment of the atomic absorption spectrometer	6
7.4.3	Spectrometric measurement of the calibration solutions	7
7.4.4	Calibration curve	7
7.5	Determination	7
7.5.1	General	7
7.5.2	Preliminary spectrometric measurement	7
7.5.3	Spectrometric measurements	7
8	Expression of results	8
8.1	Use of calibration curve	8
8.2	Use of bracketing method	8
9	Precision	8
10	Test report	9
Bibliography		11