

# DIN EN 15024-2:2018-06 (E)

## Copper and copper alloys - Determination of zinc content - Part 2: Flame atomic absorption spectrometric method (FAAS)

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Principle .....	4
4	Reagents .....	4
5	Apparatus .....	5
6	Sampling .....	5
7	Procedure .....	5
7.1	Preparation of the test portion solution .....	5
7.2	Blank test .....	6
7.3	Check test .....	6
7.4	Establishment of the calibration curve .....	7
7.5	Determination .....	9
8	Expression of results .....	10
8.1	Use of the calibration curve .....	10
8.2	Use of bracketing method .....	11
9	Precision .....	11
10	Test report .....	13
Bibliography .....		14