

# DIN EN 14941:2006-09 (E)

## Copper and copper alloys - Determination of cobalt content - FAAS method

---

<b>Contents</b>		<b>Page</b>
	<b>Foreword</b> .....	<b>3</b>
<b>1</b>	<b>Scope</b> .....	<b>4</b>
<b>2</b>	<b>Normative references</b> .....	<b>4</b>
<b>3</b>	<b>Principle</b> .....	<b>4</b>
<b>4</b>	<b>Reagents and Materials</b> .....	<b>4</b>
<b>5</b>	<b>Apparatus</b> .....	<b>5</b>
<b>6</b>	<b>Sampling</b> .....	<b>5</b>
<b>7</b>	<b>Procedure</b> .....	<b>5</b>
<b>8</b>	<b>Expression of results</b> .....	<b>9</b>
<b>9</b>	<b>Precision</b> .....	<b>10</b>
<b>10</b>	<b>Test report</b> .....	<b>11</b>
	<b>Bibliography</b> .....	<b>12</b>