

# DIN EN 15063-2:2007-01 (E)

Copper and copper alloys - Determination of main constituents and impurities by wavelength dispersive X-ray fluorescence spectrometry (XRF) - Part 2: Routine method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Principle .....	4
4	Terms and definitions .....	4
5	Apparatus .....	4
6	Sampling .....	6
7	Procedure .....	6
8	Expression of results .....	8
9	Precision .....	8
10	Test report .....	8
Annex A (informative) Conditions for the analysis .....		9
Bibliography .....		10