

# ISO/TS 13399-309:2016-03 (E)

## Cutting tool data representation and exchange - Part 309: Creation and exchange of 3D models - Tool holders for indexable inserts

---

<b>Contents</b>		<b>Page</b>
Foreword .....		vi
Introduction .....		viii
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Starting elements, coordinate systems, planes .....</b>	<b>2</b>
3.1	General .....	2
3.2	Reference system (PCS -- primary coordinate system) .....	2
3.3	Tool item position .....	2
3.3.1	Prismatic tool position .....	3
3.3.2	Round tool position .....	3
3.4	Planes .....	4
3.5	Cutting reference point (CRP) .....	5
3.6	Design of the pocket seat .....	8
3.7	Adjustment coordinate system on workpiece side .....	12
3.7.1	General .....	12
3.7.2	Designation of the coordinate system workpiece side .....	12
<b>4</b>	<b>Design of the model .....</b>	<b>14</b>
4.1	Necessary parameters for the connection interface feature .....	14
4.2	Necessary properties for insert and pocket seat .....	15
4.2.1	General .....	15
4.2.2	Properties for equilateral, equiangular and equilateral, non- equiangular inserts .....	15
4.2.3	Properties for non-equilateral, equiangular and non-equilateral, non- equiangular inserts .....	15
4.2.4	Properties for round inserts .....	16
4.2.5	Design of the pocket seat feature .....	16
<b>5</b>	<b>Tool holder for longitudinal and transversal turning .....</b>	<b>17</b>
5.1	General .....	17
5.2	Necessary properties .....	17
5.3	Basic geometry .....	18
5.4	Turning tool with pocket seat and top surface offset .....	21
5.5	Turning tool assembly .....	21
5.6	Boring bar body .....	22
<b>6</b>	<b>Turning tool for external threading .....</b>	<b>24</b>
6.1	General .....	24
6.2	Necessary properties .....	24
6.3	Basic geometry .....	25
6.4	Turning tool with pocket seat and top surface offset .....	25
6.5	Turning tool assembly .....	26
<b>7</b>	<b>Boring bar for internal threading .....</b>	<b>27</b>
7.1	General .....	27
7.2	Necessary properties .....	27
7.3	Basic geometry .....	28
7.4	Boring bar with pocket seat and top surface offset .....	29
7.5	Boring bar assembly .....	30

8	Turning tool for OD grooving and parting .....	30
8.1	General .....	30
8.2	Necessary properties .....	30
8.3	Basic geometry .....	32
8.4	Grooving tool with pocket seat and top surface offset .....	33
8.5	Grooving and cut-off tool assembly .....	33
9	Boring bar for ID grooving .....	34
9.1	General .....	34
9.2	Necessary properties .....	34
9.3	Basic geometry .....	35
9.4	Boring bar with pocket seat and top surfaces .....	36
9.5	Grooving boring bar assembly .....	37
10	Pull back boring bar .....	37
10.1	General .....	37
10.2	Necessary properties .....	38
10.3	Basic geometry .....	38
10.4	Boring bar with pocket seat and top surfaces .....	39
10.5	Pull back boring bar assembly .....	39
11	System tool for external turning .....	40
11.1	General .....	40
11.2	Necessary properties .....	40
11.3	Basic geometry .....	41
11.4	System tool with pocket seat and top surfaces .....	41
11.5	Assembly of system tool for external turning .....	42
12	System tool for external threading .....	43
12.1	General .....	43
12.2	Necessary properties .....	43
12.3	Basic geometry .....	44
12.4	System tool with pocket seat and top surfaces .....	44
12.5	Assembly of a system tool for external threading .....	44
13	System tool for internal turning .....	44
13.1	General .....	44
13.2	Necessary properties .....	45
13.3	Basic geometry .....	45
13.4	System tool with pocket seat and top surfaces .....	45
13.5	System tool for internal turning assembly .....	45
14	System tool for internal threading .....	46
14.1	General .....	46
14.2	Necessary properties .....	46
14.3	Basic geometry .....	46
14.4	System tool with pocket seat and top surfaces .....	46
14.5	System tool for internal threading assembly .....	46
15	System tool for OD grooving and/or cut-off .....	47
15.1	General .....	47
15.2	Necessary properties .....	47
15.3	Basic geometry .....	48
15.4	Grooving tool with pocket seat and top surface offset .....	48
15.5	System tool for OD grooving and parting assembly .....	48
16	System tool for ID grooving .....	49
16.1	General .....	49
16.2	Necessary properties .....	49
16.3	Basic geometry .....	49

16.4	Grooving tool with pocket seat and top surface offset .....	49
16.5	System tool for ID grooving assembly .....	49
17	Pull back system tool .....	50
17.1	General .....	50
17.2	Necessary properties .....	50
17.3	Basic geometry .....	50
17.4	System tool with pocket seat and top surfaces .....	51
17.5	Pull back system tool assembly .....	51
18	System tool, neutral design for OD turning .....	51
18.1	General .....	51
18.2	Necessary properties .....	51
18.3	Basic geometry .....	52
18.4	System tool with pocket seat and top surfaces .....	52
18.5	System tool, neutral design for OD turning assembly .....	52
19	Design of details .....	52
19.1	Basics for modelling .....	52
19.2	Fixing threads for inserts .....	52
19.3	Contact surfaces/drive keys -- Orientation .....	52
19.4	Chamfers and roundings .....	52
20	Attributes of surfaces -- Visualization of the model features .....	52
21	Structure of the design elements (tree of model) .....	53
22	Data exchange model .....	54
	Annex A (normative) Mirror planes for left-handed tools .....	56
	Annex B (informative) Information about nominal dimensions .....	57
	Bibliography .....	58